



CLUTCH RELEASE PROBLEMS – DAEWOO

It has been found that these vehicles have an issue with the clutch release shaft bending over time causing a lack of release in these vehicles. Replacing the clutch will not improve these symptoms as the root cause is wear in the release mechanism.



If it is found that the lever is not in line with the notch then it is recommended to be replaced and these units are available for purchase and stocked under part number RSDW002

PERTH - Head Office 20 Oxleigh Drive Malaga, WA, 6090

SYDNEY 132 Gipps Road

BRISBANE 30 Neon Street Smithfield, NSW, 2164 Sumner, QLD, 4074

Melbourne 29-33 Rodeo Drive Dandenong, VIC, 3175

1300 720 728 - www.cbaus.com.au

